



1216 HARRIS STREET
CHARLOTTESVILLE
VA 22903
U.S.A.

TEL: (1) (434) 984 2304
FAX: (1) (434) 984 2709
www.inbio.com

January 2012

Re: Bovine Serum Albumin (BSA)

Effective immediately, Indoor Biotechnologies recommends the use of Bovine Serum Albumin (BSA) Fraction V manufactured by Roche Diagnostics (catalog number 03116964001) for ELISA and MARIA[™] assay buffers. Buffers prepared with BSA from other manufacturers may become cloudy even after sterile filtration, leading to increased MARIA[™] analysis time and a higher incidence of bead aggregation errors.

In accordance with Good Laboratory Practices, Indoor Biotechnologies recommends monitoring the quality of prepared buffers and advises that assay results may be affected if using BSA supplied by manufacturers other than Roche Diagnostics.

Please note that Indoor Biotechnologies Inc. has no financial conflict or other interest in Roche Diagnostics. Our recommendation is based solely on product performance.

Please contact Bryan Smith, Quality Assurance Specialist at Indoor Biotechnologies Inc. with any questions or comments regarding this matter.

Bryan Smith
Tel 434 984 2304
bsmith@inbio.com